# **SIEMENS**

#### 12.10.2024 5:59:51 AM

## 6AV3688-4CX02-0AA0



Image similar

\*\*\*Spare part\*\*\* Push Button Panel PP17-I, 1 to 4 F-DI for emergency stop, with PROFIsafe communication 16 short-stroke keys, 16 surface LEDs, max. 14 DI and 14 DO terminals PROFIBUS DP12

Product was deleted without replacement If you need assistance please contact our local Siemens office

List Price	Show prices
Customer Price	Show prices
DataSheet in PDF	Download
Service & Support (Manuals, Certificates, FAQs)	Download

### **Product**

Article Number (Market Facing Number)	6AV3688-4CX02-0AA0
Product Description	***Spare part*** Push Button Panel PP17-I, 1 to 4 F-DI for emergency stop, with PROFIsafe communication 16 short- stroke keys, 16 surface LEDs, max. 14 DI and 14 DO terminals PROFIBUS DP12
Product family	Not available
Product Lifecycle (PLM)	PM500:Discontinued Product or end of PLM & Support
PLM Effective Date	End of product lifecycle since: 01.10.2023
Notes	Product was deleted without replacement If you need assistance please contact our local Siemens office
Price data	
Region Specific PriceGroup / Headquarter Price Group	S20 / 2ET
List Price	Show prices
Customer Price	Show prices
Surcharge for Raw Materials	None
Metal Factor	None
Delivery information	
Export Control Regulations	ECCN: EAR99H / AL: N
Estimated dispatch time (Working Days)	On request
Net Weight (kg)	1,624 Kg
Packaging Dimension	26,90 x 30,30 x 9,30
Package size unit of measure	CM
Quantity Unit	0 Piece
Packaging Quantity	1
Additional Product Information	
EAN	Not available
UPC	662643395945
Commodity Code	85371098
LKZ_FDB/ CatalogID	ST80XY
Product Group	3431
Group Code	R141
Country of origin	Germany
Compliance with the substance restrictions according to RoHS directive	not available
Product class	D: products made to order / customer's specifications, requiring engineering services, which cannot be re-used or utilized (design to customer)
WEEE (2012/19/EU) Take-Back Obligation	No
REACH Art. 33 Duty to inform according to the current list of candidates	
SCIP number	Not available
Classifications	
	Not available